



2 施工資料

3) 工事写真

南面⑦	1	鉄柵部塗装	施工前
			
南面⑦	2	鉄柵部塗装	ケレン
			



2 施工資料

3) 工事写真

南面⑦	3	鉄柵部塗装	下塗
			
南面⑦	4	鉄柵部塗装	中塗
			

2 施工資料

3) 工事写真

南面⑦	5	鉄柵部塗装	上塗
 A photograph of a construction site. On the left, a brick wall has a white checklist with a green border. The checklist is titled '鉄部塗装' (Iron part painting) and includes the following items: '施工前' (Before work) with a checked box, 'ケレン' (Cleaning) with a checked box, '下塗り' (Primer) with a checked box, '中塗り' (Intermediate coat) with a checked box, '上塗り' (Top coat) with a checked box, and '完了' (Completed) with an unchecked box. A circular logo with the number '10' is in the top left corner. In the foreground, a white metal railing is being painted with a grey roller. A white mesh sheet is visible in the background.			
南面⑦	6	鉄柵部塗装	完了
 A photograph of the same construction site as in the previous image. The white metal railing is now fully painted and appears clean. The checklist on the brick wall remains the same, with the '完了' (Completed) box now checked. The rest of the scene, including the brick wall and the white mesh sheet, is identical to the previous image.			