

2 施工資料

3) 工事写真

南面④	1	タイル張替工事	施工前										
 <p>A photograph showing a wall made of grey concrete blocks. A white checklist with a green border is taped to the wall. The checklist is titled 'タイル張替' (Tile Replacement) and has a circled '5' in the top left corner. The checklist items are:</p> <table border="0"><tr><td><input checked="" type="checkbox"/> 施工前</td><td><input type="checkbox"/> タイル貼付</td></tr><tr><td><input type="checkbox"/> 既存脆弱部撤去</td><td><input type="checkbox"/> タイル目地埋め</td></tr><tr><td><input type="checkbox"/> 目荒らし</td><td><input type="checkbox"/> 酸締め</td></tr><tr><td><input type="checkbox"/> ハイフレ塗布</td><td><input type="checkbox"/> 完了</td></tr><tr><td><input type="checkbox"/> 下地調整</td><td></td></tr></table> <p>The wall has a horizontal metal rail and a white pipe on the right side. A yellow vertical mark is visible on the wall to the right of the checklist.</p>				<input checked="" type="checkbox"/> 施工前	<input type="checkbox"/> タイル貼付	<input type="checkbox"/> 既存脆弱部撤去	<input type="checkbox"/> タイル目地埋め	<input type="checkbox"/> 目荒らし	<input type="checkbox"/> 酸締め	<input type="checkbox"/> ハイフレ塗布	<input type="checkbox"/> 完了	<input type="checkbox"/> 下地調整	
<input checked="" type="checkbox"/> 施工前	<input type="checkbox"/> タイル貼付												
<input type="checkbox"/> 既存脆弱部撤去	<input type="checkbox"/> タイル目地埋め												
<input type="checkbox"/> 目荒らし	<input type="checkbox"/> 酸締め												
<input type="checkbox"/> ハイフレ塗布	<input type="checkbox"/> 完了												
<input type="checkbox"/> 下地調整													
南面④	2	タイル張替工事	既存タイル撤去中										
 <p>A photograph showing the same wall as in the previous image, but now during the removal of existing tiles. A checklist with a green border is taped to the wall. The checklist is titled 'タイル張替' (Tile Replacement) and has a circled '5' in the top left corner. The checklist items are:</p> <table border="0"><tr><td><input checked="" type="checkbox"/> 施工前</td><td><input type="checkbox"/> タイル貼付</td></tr><tr><td><input checked="" type="checkbox"/> 既存脆弱部撤去</td><td><input type="checkbox"/> タイル目地埋め</td></tr><tr><td><input type="checkbox"/> 目荒らし</td><td><input type="checkbox"/> 酸締め</td></tr><tr><td><input type="checkbox"/> ハイフレ塗布</td><td><input type="checkbox"/> 完了</td></tr><tr><td><input type="checkbox"/> 下地調整</td><td></td></tr></table> <p>The wall shows signs of active work, with a hole being drilled into the mortar joint between two tiles. A black power drill is visible at the bottom center of the frame. A brown paper bag is partially visible at the bottom left.</p>				<input checked="" type="checkbox"/> 施工前	<input type="checkbox"/> タイル貼付	<input checked="" type="checkbox"/> 既存脆弱部撤去	<input type="checkbox"/> タイル目地埋め	<input type="checkbox"/> 目荒らし	<input type="checkbox"/> 酸締め	<input type="checkbox"/> ハイフレ塗布	<input type="checkbox"/> 完了	<input type="checkbox"/> 下地調整	
<input checked="" type="checkbox"/> 施工前	<input type="checkbox"/> タイル貼付												
<input checked="" type="checkbox"/> 既存脆弱部撤去	<input type="checkbox"/> タイル目地埋め												
<input type="checkbox"/> 目荒らし	<input type="checkbox"/> 酸締め												
<input type="checkbox"/> ハイフレ塗布	<input type="checkbox"/> 完了												
<input type="checkbox"/> 下地調整													

2 施工資料

3) 工事写真

南面④	3	タイル張替工事	目荒し
			

南面④	4	タイル張替工事	ハイフレ塗布
			

南面④	5	タイル張替工事	下地調整
-----	---	---------	------



南面④	6	タイル張替工事	タイル張付
-----	---	---------	-------



2 施工資料

3) 工事写真

南面④	7	タイル張替工事	目地入れ
			

南面④	8	タイル張替工事	酸締め
			

2 施工資料

3) 工事写真

南面④	9	タイル張替工事	完了
			